

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	AMEREN ILLINOIS COMPANY
Inspection Unit(s):	Hoopeston
Date of Meeting:	03/18/2015
Pipeline Safety Analyst:	Aaron McElravy
Exit Meeting Contact:	Steve Barkley

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

2012-S001-00009 (Code Part [192.479a]) - Staff field verified remedial measures were taken to address deficiencies identified on a previous field audit conducted on December 6, 2011. Staff inspected customer meters and regulators at 904 and 909 Sprague Road in Hoopeston for adequate coatings to prevent atmospheric corrosion. This issue will be considered closed based upon this field audit and the corrective action taken.


Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:



Operator Representative Signature:

